# Fiber optic cable cannot be threaded through the protective sleeve



## Overview

Our Splice Protector Sleeves (SPS40 and SPS60) can fit fibers with an outer diameter up to 900 µm, protecting the spliced fibers from bending or flexing at the splice joint.

## Key Takeaways

Fiber optic cables must have the protective sleeve threaded before fusion splicing; attempting to insert it afterward can be extremely difficult or impossible.

### Common Causes

Incorrect Installation Sequence The protective sleeve must be slid onto the fiber before performing the fusion splice. If the splice is already completed, the sleeve cannot be threaded without cutting and restarting the fiber preparation. Sleeve Size and Fiber Alignment Fiber diameters are extremely small (around 250 microns), while sleeve openings range from 1 mm to 2 mm.

Misalignment or a slightly bent fiber can make threading nearly impossible. Contamination or Debris Dust, oils, or leftover coating on the fiber can obstruct the sleeve. Even minor debris can prevent smooth insertion.

Solutions and Best PracticesPre-Thread the Sleeve Always slide the protective sleeve onto the fiber before stripping and cleaving. This ensures the sleeve is in place and ready to cover the splice immediately after fusion. Use Specialized Tools Tools like the Quick Sleever® PSI-15 can simplify threading by holding and aligning the fiber with the sleeve, reducing the risk of bending or misalignment.

*© 2026 EXF OPTICAL NETWORKS - All rights reserved*

Check Sleeve Compatibility Ensure the sleeve diameter matches the fiber type. Mini or micro sleeves may require more precise handling, while standard sleeves are easier to thread. Handle Fibers Carefully Avoid bending or twisting the fiber during insertion.

Keep the fiber straight and use gentle, steady pressure to guide it into the sleeve. Clean the Fiber Wipe the fiber with a dust-free cloth and alcohol before threading to remove any contaminants that could block the sleeve. Consider Alternative Sleeving For challenging environments or pre-terminated fibers, self-wrapping sleeves like ROUNDIT® 2000 NX VTR provide protection without requiring heat or precise threading, offering easier installation and reusability.

### Key Takeaway

The inability to thread a fiber optic cable through a protective sleeve is usually due to improper sequencing, misalignment, or contamination. Pre-threading the sleeve, using alignment tools, and handling the fiber carefully are essential steps to ensure successful installation and long-term splice protection.

## Article Content

Comprehensive Guide to Fiber Optic Splice Sleeve

Whether you''re building new FTTH networks or maintaining existing ones, this guide will walk you through the types, materials, applications, and best

Temporary Fiber Splices

Our Splice Protector Sleeves (SPS40 and SPS60) can fit fibers with an outer diameter up to 900 μm, protecting the spliced fibers from bending or flexing at the splice joint. They provide rigid support and

Fiber Splicing & Winding Tutorial – Step-by-Step Guide

Note: Beware of fiber end surface contamination, the fiber protection sleeve should be threaded before fiber stripping. It is strictly forbidden to penetrate after the end face is prepared.

All You Need to Know About Fiber Protection Sleeves

First, slide the protection sleeve onto the fiber (this can be very challenging so we recommend using the Quick Sleever® PSI-15). Then, perform the fusion splice.

Fiber Optic Cable Protection Sleeves: When Heat Shrink Isn''t the Best ...

Learn when heat shrink is the wrong tool for protecting fiber optic cables—and what to use instead.

*© 2026 EXF OPTICAL NETWORKS - All rights reserved*

Fiber Optic Cable Protection Sleeve Installation Guide

Gently test the cable to verify that the fiber optic cable protection sleeve does not slide or rotate. A stable sleeve confirms long-term protection and correct installation.

Fiber Splicing Methods and Protection with Splice Closures

Discover the differences between fusion and mechanical splicing, learn how to ensure safe fiber optic splicing, and see why splice closures are essential for long-term network reliability.

Fibre Optic Cable Splicing Guidelines | PDF | Optical Fiber | Wire

The document provides guidelines for splicing fibre optic cable. It outlines the necessary tools, materials and steps for preparing the cable ends, splicing the optical fibers using fusion splicing, reinforcing the

Splice Sleeves Protection Fiber Optic | iFiber Optix

Ribbon splice sleeves are required when splicing fiber ribbon — multi-fiber flat ribbon cables where all fibers in the ribbon are mass-fused simultaneously. Standard round splice sleeves cannot

Fiber Optic Splice Protection Sleeves | Reliable Splice

The main purpose of a fiber optic splice protection sleeve is to provide mechanical reinforcement and environmental sealing for a bare fusion splice. It protects the

The Most Comprehensive Guide Of Optical Modules

Explore the ultimate guide to optical modules. Learn types, functions, performance metrics & how to choose the right module for your fiber network.

10 Best Fiber Optic Fusion Splicer Machines (June

Discover the 10 best fiber optic fusion splicer machines (June 2026). Our expert reviews highlight reliable, high-precision splicers ideal for efficient

The Complete Guide to Fiber Optic Cable Management

Ultimate fiber optic cable management guide: Best practices for installation, organization & maintenance - ensure network reliability.

Fiber Optic Connectors

ST Fiber Optic Adapter 4.52 x 10 mm Fiber Optic Connectors Available on back order +1: $966.62/each +5: $889.29/each +10: $850.63/each Available on back order

E56E-EN-07+FiberOpticSensors

*© 2026 EXF OPTICAL NETWORKS - All rights reserved*

Our global manufacturing network for fiber optic sensors in Ayabe (Japan), Shanghai (China) and Nufringen (Germany) focuses on continuously optimising methods for small and large volume

The FOA Reference For Fiber Optics

Passive loss is made up of fiber loss, connector loss, and splice loss. Don''t forget any couplers or splitters in the link. If the specifications for a type of system or network are not known, industry

Optical fiber connector

An optical fiber connector is a device used to link optical fibers, facilitating the efficient transmission of light signals. An optical fiber connector enables quicker

Submarine communications cable

Submarine cables are made of copper or optical fibers, surrounded by several protective layers of plastic, wire or synthetic materials. Cables can also be composed of dielectric fluids or hydrocarbon

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

## Contact Us

Continue your research online:

Website: https://explosivefunctions.co.za
Technical inquiry: https://explosivefunctions.co.za/contact.html
EU project coordination: Parque das Nações, Lisbon, Portugal

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

*© 2026 EXF OPTICAL NETWORKS - All rights reserved*