How to remove the optical adhesive from pigtails



Overview

Safely and effectively removing optical adhesives is a critical skill in manufacturing and product lifecycle management.

Key Takeaways

Optical adhesive on fiber pigtails can be safely removed using a combination of careful mechanical scraping and compatible solvents, while avoiding prolonged exposure that could damage the fiber coating.

Understanding the Adhesive

Optical pigtails often use UV-curable or epoxy adhesives to bond the fiber to the connector, creating a strong, durable joint. These adhesives are chemically resistant and require careful handling to remove without damaging the fiber or connector.

Mechanical Removal

Use plastic scrapers, razor blades, or specialized fiber cleaning tools to gently trim away cured adhesive. Avoid excessive force to prevent scratching the fiber or connector ferrule. Remove any large adhesive beads first before applying solvents.

Chemical Solvent Cleaning

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Apply isopropyl alcohol (IPA) or fiber-safe commercial cleaning agents in small amounts using a lint-free cloth or towelette. For stubborn adhesive, acetone or specialized optical adhesive removers can be used sparingly, ensuring the fiber is not soaked. Limit exposure time to prevent coating delamination, as prolonged contact can cause the acrylate coating to swell and separate from the glass.

After solvent application, dry the fiber immediately with a lint-free cloth to remove residue.

Thermal Techniques

Some adhesives, particularly heat-cured epoxies, can be softened with controlled heat. Use a low-temperature oven or heat gun carefully to avoid exceeding the fiber's thermal tolerance. Once softened, the adhesive can be gently scraped or wiped away.

Best Practices

Work in a clean, dust-free environment to prevent contamination during cleaning. Always wear gloves to avoid oils from your hands contaminating the fiber. Test any solvent or method on a non-critical fiber section first to ensure compatibility.

Avoid soaking the fiber in solvents; instead, use minimal application and wiping strokes. By combining mechanical trimming, solvent cleaning, and careful thermal softening, optical adhesive can be removed from pigtails safely, preserving fiber integrity and ensuring reliable splicing or connector performance.

Article Content

The Unsticking Challenge: How to Safely Remove Optical Adhesives

Safely and effectively removing optical adhesives is a critical skill in manufacturing and product lifecycle management. It requires a methodical approach, a good understanding of adhesive

The FOA Reference For Fiber Optics

In a few minutes, the glue is melted, so you remove the connector, insert the stripped fiber, let it cool and it is ready to polish. Fast and easy, low loss, but not

Cleaning Techniques for Pigtails and Patch Cords

This section describes cleaning techniques for pigtails and patchcords. Note: No known cleaning methods are 100% effective; therefore, it is imperative that inspection is included as part of the

Fiber U Lesson Plan: Basic Fiber Optic Skills Lab

© 2026 EXF OPTICAL NETWORKS - All rights reserved

It is recommended that everyone do at least one of the adhesive/polish connectors and one prepolished/splice connector type. We have provided step-by-step

Preparing your Fiber Optic Cable for Connectors or Splices

From removing the outer jacket to cleaning the bare fiber and achieving a perfect cleave, each stage demands attention to detail and the use

Inspection and Cleaning Procedures for Fiber-Optic Connections

This document describes inspection and cleaning processes for fiber optic connections. It is important that every fiber connector be inspected and cleaned

"Fiber Splicing Pigtails | Step-by-Step Guide for Beginners"

In this detailed video, we''ll walk you through the fiber optic pigtail splicing process — from preparation to final testing.

3 Common Methods to Terminate Connectors on Fiber Cable

These three methods use “Epoxy Style Connectors,” “Pre-Polished Style Connectors,” or “Fiber Optic Pigtails.” Each of these methods has several advantages as well as some

Terminating Fiber in the Field

There are three primary methods for terminating fiber connections in the field: adhesive connections with field polishing, mechanical connectors without polishing, and fusion splicing utilizing pigtail assemblies.

The Unsticking Challenge: How to Safely Remove Optical Adhesives

In the precise world of optical manufacturing and assembly, the application of optical adhesives is a critical step for achieving robust and optically clear bonds. However, there are times

What Is Fiber Optic Pigtail and How to Splice It?

ST Fiber Optic Pigtail: ST pigtail connector is the most popular connector for multimode fiber optic LAN applications. It has a long 2.5mm diameter ferrule made of ceramic (zirconia),

Fiber cable termination

Fiber Optic cable termination is the addition of connectors to each optical fiber in a cable. The fibers need to have connectors fitted before they can attach to other equipment. Two common solutions for

How to choose fiber optic pigtails?

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Applications Fiber optic pigtails are used to terminated fiber optic cables via fusion splicing or mechanical splicing as shown in the picture below. The end of the pigtail is stripped and fusion spliced to a single fiber or a multi-fiber trunk.

How to Install Fiber Optic Pigtails (Step-by-Step Guide)

Introduction Installing fiber optic pigtails correctly is essential for ensuring low signal loss and long-term reliability.

Co-Packaged Optics (CPO) Market Analysis: 1.6T Transition & AI

Strategic analysis of the Co-Packaged Optics (CPO) market, tracking the 2026 inflection point for 1.6T modules. Explores value migration, supply chain bottlenecks, and thermal

Understanding Fiber Optic Pigtails: A Quick Guide

Understanding Fiber Optic Pigtails Fiber optic pigtails are an essential component in the installation and termination of fiber optic cables. They are a short length of optical fiber that has been

5 Helpful Tips to Eliminate Orbital Sander Pig Tails / Swirl Marks

In this video Bethany from Madeline Jean Antiques & Restoration shares 5 helpful tips on how to eliminate orbital sander pig tail/swirl marks on wood. ****FO...

How to Splice fiber pigtails?

Fiber optic pigtails are available in various types: Grouped by pigtail connector type, there are LC fiber optic pigtails, SC fiber pigtails and ST fiber pigtails, etc. By fiber type, there are single-mode fiber

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Contact Us

Continue your research online:

Website: https://explosivefunctions.co.za
Technical inquiry: https://explosivefunctions.co.za/contact.html
EU project coordination: Parque das Nações, Lisbon, Portugal

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 EXF OPTICAL NETWORKS - All rights reserved