How to use the Newport optical power meter



Overview

The Newport 70310 optical power meter user manual provides detailed information on how to operate and interface with this advanced, microprocessor-based instrument.

Key Takeaways

Using a Newport optical power meter involves connecting the detector, powering the device, zeroing, selecting the measurement range, and reading the optical power accurately. Step 1: Inspect and Set Up the DeviceBefore use, inspect the optical power meter and detector for any damage. Ensure the detector is compatible with your meter model (e.g., 70310, 840-C, 1917-R, 1936/2936-C) and mount it securely on an optical stand if required.

For handheld models like the 840-C, align the memory module with the meter head and slide it into place until the connector engages. Step 2: Power OnTurn on the meter using the front panel switch or control key. Some models, like the 1917-R, require holding the power button for a few seconds.

Enable backlighting if needed for better visibility in low-light conditions. Ensure batteries are charged or use the recommended external power supply to avoid damage. Step 3: Zero the MeterZeroing is essential for accurate measurements.

Allow the reading to stabilize, then press the zero button for 2–3 seconds. The meter will display a confirmation (e.g., “Zero”) and return to measurement mode. This compensates for dark current and ambient light.

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Step 4: Connect the DetectorAttach the optical detector to the meter using the designated input jack (e.g., DB-15 for 1917-R). Ensure the connection is secure and the detector is recognized by the meter. If the meter displays “Bad Detector,” check compatibility and connections.

For meters with calibration modules, ensure the module is properly seated to provide accurate calibration data. Step 5: Select Measurement ParametersChoose the appropriate measurement range (current or voltage) and mode (steady-state, modulated, RMS, or peak-to-peak) depending on your application. Some meters allow manual range selection or automatic range adjustment.

For A

C or modulated signals, ensure the bandwidth setting matches your signal frequency. Step 6: Take MeasurementsAlign the optical source with the detector carefully. Observe the reading on the LCD or digital display.

For meters with audio indicators, you can maximize the signal without looking at the display. Record the optical power in the desired units (e.g., watts, milliwatts, dBm). Step 7: Optional Computer InterfaceMany Newport meters support GPIB, RS-232, or USB connections for remote control and data logging.

Connect the meter to a PC using the appropriate interface and software to automate measurements or record data over time. Step 8: Power Off and StoreAfter measurements, turn off the meter and disconnect the detector. Store the meter and detectors in a clean, dry environment to maintain calibration and prevent damage.

Safety and Best Practices

Always use the recommended power supply to prevent damage. Avoid exposing the detector to optical power beyond its rated range. Handle optical fibers and detectors carefully to prevent misalignment or contamination.

Follow the manufacturer's instructions for calibration and firmware updates to ensure accurate readings. By following these steps, you can effectively operate a Newport optical power meter for precise optical power measurements in laboratory or industrial settings.

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Article Content

Newport 70310 Optical Power Meter User Manual | Manualzz

The Newport 70310 optical power meter user manual provides detailed information on how to operate and interface with this advanced, microprocessor-based instrument.

Optical Power Meter 1928-C User''s Manual

Download the User''s Manual for the Newport 1928-C Optical Power Meter, which measures optical power and energy of near-monochromatic or monochromatic sources. This manual covers features,

NEWPORT 841-PE USER MANUAL Pdf Download | ManualsLib

Appropriate installation must be done for water-cooled and fan-cooled detectors. Refer to the specific instructions for more information. The user must wait for a while before handling these detectors after

Optical Power Meters

Optical power meters and detectors have been served by Newport for over 30 years. The offering ranges from a low cost, hand-held meter to the most advanced dual channel benchtop power meter

NEWPORT 840-C OPERATOR''S MANUAL Pdf

Please carefully read this instruction manual before using Getting Started the Model 840-C HandHeld Power Meter. Alignment of the detector may require care and

MULTIFUNCTION OPTICAL POWER METER

FAMILIARIZATION This section contains detailed information needed to prepare and operate the Model 70310 Optical Power Meter for independent operation as a voltage or current measurement

Model 1918 Series Power Meters Manual

At the end of the charging time, the Optical Meter can be used without the external power supply. For the highest precision and accuracy, the 1918-C Optical Meter should be allowed to warm up for one

Benchtop Optical Power Meters

A: The 1936-R and 2936-R power meters are designed with user selectable analog and digital filtering options. To measure a CW light source, apply the heaviest filtering, and to measure a modulated

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Microsoft Word

Other important information regarding the use and operation of the power meter is included in the complete User''s Manual. The complete User''s Manual in Adobe PDF format, and the instrument

843-R/843-R-USB Power Meter Manual | PDF | Backlight

It provides instructions on how to use the laser power meter with different types of sensors including: 1) Thermal sensors for measuring laser power and energy, including how to set the laser wavelength,

Optical Power and Energy Meters

Thorlabs'' expanding line of optical power and energy meters includes a large selection of sensor heads, single- and dual-channel power and energy meter

Optical Power Meter: A Tool for Measuring Fiber Optic Power

An optical power meter is a device used to measure the power of an optical signal. It is a valuable tool for fiber optic technicians, as it can be used to measure the power of a variety of fiber optic devices,

Optical Power Meter Basics

Introduction An optical power meter measures the photon energy in the form of current or voltage from an optical detector such as a semiconductor, a thermopile, or a pyroelectric detector. Newport''s

How to Test Optical Transceiver Modules: Methods, Metrics & Best ...

Learn how to test optical transceiver modules using power meters, BERT testers, and DDM tools. Ensure compatibility, performance, and reliability in data center and enterprise networks.

Company Overview

Our acquisition of ILX Lightwave expanded our photonics instrumentation and systems offerings, adding to our product portfolio ILX''s diode laser controllers and drivers, temperature controllers, current

FTBx-1750 High-performance power meter | Product | EXFO

Description An optical power meter that meets all your power measurement requirements Designed for the new LTB-8 Rackmount Platform, the FTBx-1750 High-Performance Power Meter and the OHS

Integrating Sphere Fundamentals and Applications

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Integrating Sphere Fundamentals and Applications An integrating sphere collects electromagnetic radiation from a source completely external to the optical device, usually for flux measurement or

Laser Power Meter Market 2026 Trends and Forecasts 2034:

Laser power meters are crucial tools for measuring the power output of lasers, ensuring their accurate performance in various applications. This report provides a comprehensive overview of the global

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: https://explosivefunctions.co.za
Technical inquiry: https://explosivefunctions.co.za/contact.html
EU project coordination: Parque das Nações, Lisbon, Portugal

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 EXF OPTICAL NETWORKS - All rights reserved