Method for splicing and stripping composite optical cables



Overview

Fiber optic splicing, crucial for maintaining seamless connectivity in modern communication networks, primarily uses two methods: fusion splicing and mechanical splicing.

Key Takeaways

Composite optical cables are stripped and spliced using a combination of mechanical or fusion splicing techniques, with careful preparation of the fiber ends and removal of protective layers to ensure low-loss, reliable connections.

Stripping Composite Optical Cables

Remove the outer jacket and armor: Use a cable stripper to carefully peel off the outer plastic or armored layers without damaging the inner fibers. For composite cables, this may include multiple layers of protective sheaths and aramid yarns. Expose buffer tubes and fibers: Strip the buffer tubes to access the individual fibers.

Typical stripping lengths range from 3–5 cm for single fibers, and 50–100 cm for the outer cable jacket depending on the splice closure. Clean water-blocking gel: If the cable contains gel, carefully remove it using a lint-free cloth with a small amount of high-purity alcohol (99% isopropyl recommended) to avoid contamination or damage to the fiber coating. Strip the fiber coating: Use a mechanical fiber stripper to remove the protective coating from the fiber.

Minimize the number of passes to prevent surface flaws that could weaken the fiber.

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Preparing Fibers for Splicing

Insert fiber protection sleeves: Place sleeves on the fibers before stripping to protect the bare fiber during handling and splicing. Clean the fiber ends: Wipe the stripped fiber with alcohol and a dust-free cloth to remove debris and ensure a clean end-face. Cleaving: Use a fiber cleaver to cut the fiber end precisely.

Proper cleaving is critical for low-loss splicing.

Splicing Methods

Fusion Splicing

Process: Align the cleaved fiber ends in a fusion splicer, which uses an electric arc to melt and fuse the fibers into a continuous optical path. Advantages: Produces the lowest signal loss (typically

Article Content

The Ultimate Guide to Splicing of Fiber: Techniques and Tips

Fiber optic splicing, crucial for maintaining seamless connectivity in modern communication networks, primarily uses two methods: fusion splicing and mechanical splicing.

Fiber Optic Cable Splicing Methods: A Practical Guide

The two primary industry-accepted methods for fiber optic cable splicing are fusion splicing and mechanical splicing. The choice between them depends on performance requirements,

Fiber Splicing & Winding Tutorial – Step-by-Step Guide

Learn fiber splicing and winding in 5 steps with pro tips on stripping, cleaving, fusion, and sleeve protection. Ensure low-loss, reliable fiber connections.

Fiber optic cable splicing and termination steps Guide

① Before stripping, check whether the connected optical cable is damaged or squeezed and deformed; ② Straighten out the optical cable and make reservations according to the regulations;

Fibre Optic Cable Splicing Method | PDF | Home & Garden

The document provides steps for pulling and splicing fiber optic cable. It outlines precautions to take when uncoiling and laying the cable to avoid kinks. It also details installing pulleys to prevent excess

Fiber U Basic Skills Lab Workbook-splicing

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Fusion splicing starts with preparing the cable for splicing by stripping sufficient jacket length to expose the proper length of buffer tubes (if loose tube cable) and buffered fiber for the splice closure chosen.

Preparing your Fiber Optic Cable for Connectors or Splices

In this guide, we''ll walk you through the entire process of preparing fiber optic cable for splicing and termination to fiber connectors. We''ll explore the

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best practices, loss standards (ITU-T G.652), cost analysis, and FAQs for

Fiber Optic Splicing: A Complete Guide | Jonard Tools

Using professional-grade tools ensures accuracy, efficiency, and safety throughout the process. Step 3: Prepare the Cable for Splicing Begin by carefully removing

The FOA Reference For Fiber Optics

The connection loss of this type of termination includes the typical connection loss tested when mated to a reference connector plus the splice used to attach the

Fusion Splicing Basics (Part 3): Methods, Practices and

This blog is the third and final in a series of blogs that overview fusion splicing equipment and methods, particularly those of interest to the

Optical Fiber Splicing 01 – From Preparation To Cleaning

Do you know how fiber optic cables are joined together to transmit data over long distances? In this article, I will provide an insight into the fascinating process of optical fiber splicing. Fusion splicing is

Fiber Splicing & Winding Tutorial – Step-by-Step Guide

The operation and skills of fiber optic fusion splicing technology can be mainly divided into five steps: fiber stripping, fiber cutting, fiber melting, fiber sleeve, and fiber winding. And tools

How to Splice Fiber Optic Cables?

Do you really know how to splice the fiber optic cable? The intrinsic transmission loss of optical fiber is largely determined, but the splicing loss at the fiber optic

Fiber Optic Cable Splice: The Most Complete Guide

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Fiber optic cable splicing stands as the foundational skill enabling this vision, expertly uniting fiber strands to maintain flawless signal transmission.

Splicing for Fiber Optic Cable: A Comprehensive Guide

Fiber optic splicing is the process of joining two fiber optic cables to create a continuous path for optical signals. This comprehensive guide covers splicing fundamentals, techniques,

What is Fiber Optic Cable Splicing?

Fusion splicing is used by many telecommunications and cable television providers for long-haul single-mode networks, although mechanical splicing is used for shorter local cable lengths.

The FOA Reference For Fiber Optics

In addition to the splicer and cleaver, the tech doing the splicing will need a set of cable preparation and fiber stripping tools. Since much fusion splicing is done in the outside plant, the splicing tech should

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

Contact Us

Continue your research online:

Website: https://explosivefunctions.co.za
Technical inquiry: https://explosivefunctions.co.za/contact.html
EU project coordination: Parque das Nações, Lisbon, Portugal

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 EXF OPTICAL NETWORKS - All rights reserved