Methods for separating multimode optical fibers in a fiber fusion splicer



Overview

Fusion splicing may be done one fiber at a time or a complete fiber ribbon from ribbon cable at one time.

Key Takeaways

Multimode fibers are separated and prepared for fusion splicing through precise stripping, cleaning, cleaving, and alignment, using either mechanical or optical core alignment techniques.

Fiber Stripping and Cleaning

Before splicing, the coating of multimode fibers (typically 250 µm or 900 µm) must be removed to expose the bare glass. Precision strippers with adjustable tension are recommended to avoid microbends or nicks in the fiber core ( ). The stripped fiber should be cleaned with lint-free wipes and 99% isopropyl alcohol to remove any contaminants, as residues can affect cleaving and splicing quality ( ).

Stripping lengths usually range from 10–20 mm, depending on the splicer and fiber type ( ).

Fiber Cleaving

A high-quality cleave is critical for multimode fibers due to their larger core and graded-index profile. The fiber is inserted into a precision cleaver, which scores and breaks the fiber to produce a flat, perpendicular end face ( ). Proper cleaving ensures minimal splice loss and reduces the risk of misalignment during fusion.

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Alignment Techniques

Multimode fibers can be more challenging to align than single-mode fibers because of their larger core and multiple light paths ( ). Two main alignment methods are used: Profile (Optical Core) Alignment: The splicer illuminates the fiber cores from multiple directions, and software automatically aligns the fibers using movable stages to maximize core overlap ( ).

LI

D (Local Injection and Detection) Alignment: Light is coupled into one fiber, and the transmission through the other fiber is measured while adjusting the fiber positions to optimize light coupling ( ). These methods ensure that the multimode cores are properly matched, reducing transition losses even when fibers have slightly different core diameters or refractive index profiles ( ).

Splicing and Protection

Once aligned, the fibers are fused using an electric arc, CO_2 laser, or other heating methods to create a permanent molecular bond ( ). After fusion, a protective heat-shrink sleeve is applied to safeguard the splice from environmental damage ( ).

Practical Tips

Multimode splicing is generally less critical than single-mode, but mismatched core sizes or fiber types can still cause significant losses ( ). Always follow the manufacturer's recommended cleave lengths and splicing parameters for the specific splicer model ( ). Practice and familiarity with the splicer improve alignment accuracy and reduce splice loss, especially for multimode fibers with graded-index profiles ( ).

By carefully following these steps—stripping, cleaning, cleaving, precise alignment, and proper fusion—technicians can achieve low-loss, reliable multimode fiber splices suitable for high-performance optical networks.

Article Content

Fusion Splicing of Fibers – electric discharge, fusion

This article explains the principle of fusion splicing, a common method for making permanent low-loss fiber splices by melting and fusing two fiber ends together,

The FOA Reference For Fiber Optics

Fusion splicing may be done one fiber at a time or a complete fiber ribbon from ribbon cable at one time. First we''ll look at single fiber splicing and then ribbon

Fusion splice techniques for multicore fibers

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Fusion splice techniques for multicore fibers (MCFs) are discussed here. We demonstrate a swing electrode system for uniform discharge and an end-view function for automatic and precise

Fiber Optic Splicing Techniques Guide | PDF | Optical Fiber

The document outlines the methodology for fiber optic splicing, detailing both fusion and mechanical splicing techniques. Key steps include preparation of the fibers, splicing processes, testing for signal

Optical Fiber Fusion Splicing | Springer Nature Link

This book is an up-to-date treatment of optical fiber fusion splicing incorporating all the recent innovations in the field. It provides a toolbox of general strategies and specific techniques that the

How to Splice Fiber Optic Cable – Step-by-Step Fusion Splicing Guide

Learn how to splice fiber optic cable using fusion splicing with this complete step-by-step guide. Includes tools, best practices, loss standards (ITU-T G.652), cost analysis, and FAQs for

Mastering Optical Fiber

Learn fiber fusion splicing steps, tools, and troubleshooting with Weunion AI9/AI10 splicers & NK3200/NK4000 OTDRs. Optimize precision for FTTH, 5G, and data centers.

Fusion Splicing Basics (Part 3): Methods, Practices and Testing

The preparation process before inserting the fiber into the splicer is important. Let''s discuss fiber splicing methods, practices and testing.

Fusion-splice basics

From start to finish, the fusion-splicing process has four main steps: 1.) preparing the cable and fiber ends, 2.) fusing the fiber ends together, 3.) adding-splice protection or re-coating the

Research on fusion splicing technology of 7-core fiber

The long-distance 7-core optical fiber was used to simulate the engineering application scenario and a new splicing method controlled by algorithm program was used in the experiment.

Fusion Splicing of Fibers – electric discharge, fusion

Fusion splicing of fibers is a technique of making low-loss fiber joints by fusing fiber endfaces together. It is widely used in fiber optics.

Fiber Optic Pigtail: The Complete Guide to Types,

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Confused about fiber optic pigtails—which connector type, which polish, fusion or mechanical splice? Our guide covers LC vs SC, APC vs UPC,

How to choose fiber optic pigtails?

High quality fiber pigtails combined with correct fusion splicing practices offer the best performance for fiber optic cable termination. 99% of single mode

Ribbon Fiber Optic Cable and Splicing: Key Points and

Ribbon fiber optic cables offer high-density connectivity with efficient mass fusion splicing. Learn about their advantages, installation challenges and

Fiber Optic Pigtail: Types, Splicing Guide, Specs & Price

Fiber optic pigtail guide : SC/APC & LC/UPC connectors, 0.9/2.0/3.0 mm buffers, single-mode and multimode types, fusion splicing steps, price ranges, specifications, and how to

Basics of Fiber Optics

I. Advantages Fiber optics has many advantages over copper wire (see Table 1) including: Increased bandwidth: The high signal bandwidth of optical fibers provides significantly greater information

The Complete Guide to Fiber Optic Cable Management

Ultimate fiber optic cable management guide: Best practices for installation, organization & maintenance - ensure network reliability.

Fiber U Basic Skills Lab Workbook-splicing

Fusion splicing is the preferred method for splicing long distance singlemode cable plants, as it''s low loss and reflectance maximizes cable plant performance. Multimode fiber is more often spliced by

Related Video Reference

This video was associated with the source search result. Verify technical details against current product documentation and project requirements.

© 2026 EXF OPTICAL NETWORKS - All rights reserved

Contact Us

Continue your research online:

Website: https://explosivefunctions.co.za
Technical inquiry: https://explosivefunctions.co.za/contact.html
EU project coordination: Parque das Nações, Lisbon, Portugal

This document is for preliminary research. Verify specifications against current standards, product documentation and project requirements.

© 2026 EXF OPTICAL NETWORKS - All rights reserved